

Omission and Notes

PAD issue: doubler ERROR ON PCB. DO NOT Connect bottom jumper position (closest to ACC inlet). There is an error during PCB manufacturing and the tripler connection should be the only connection made. For triple, connect the middle and top connection. (furthest from ACC inlet) for double.